soul and		25×
-	Approve & FSS STENCE SEE 2002/1000100ETCHA SEE 13 13 14 15 14 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	90900100080-4 REPORT NO.
	INFORMATION REPORT	CD NO.
	SECRET.	
COUNTRY		DATE DISTR. 5 March 1
1 SUBJECT	Analysis of Soviet Engine Mount	NO. OF PAGES 2
		NO. OF ENCLS.
		SUPPLEMENT TO
		REPORT NO.
DATE OF	INFORMATION 4 February 1952	25/
<u> </u>		
1.	The engine mount assembly consisted of the following:	o of a trail think are
	a. One 20-inch length of 1.36-inch 0.D. tubing, with b. One 20-inch length of 0.98-inch 0.D. tubing, with	0.059-inch-thick wall.
	<ul> <li>c. Clevis.</li> <li>d. Bolt - 0.55-inch diameter by 3 inches long, hexage</li> <li>e. Hexagonal nut for the bolt described in Item d.</li> </ul>	onal head.
	The tubing and clevis were painted with a gray-green cadmium plated. The two lengths of tubing were welde 30 degrees and both, in turn, were welded to the clev metal-arc process and was of good quality by U. S. st	is. Welding was done by the
2.		
3.	Spectrographic and Chemical Analyses:	
<b>)•</b>	g	t parts (a) thru (c) above
	were generally in accordance with Seviet specific	ation 30 x CA.
		<i>7</i>
		~
1		
1	*	
i /		

CLASSIFICATION SECRET SECRET

			~_	•	011 10/11/1		- 1
STATE	X	NAVY			NSRB	DISTRIBUTION	┨
ARMY	文	AIR		X	FBI	ORR EV	لـ

The specification for this type of steel is:

Steel Type: C Mn Si Cr Ni S P 30x C ca .0.28-0.35 0.8-1.1 .09-1.1 0.8-1.1 0.3 0.04 0.04

Part (d) was made from a plain 0.50 per cent carbon steel corresponding to AISI specification C 1050 (USSR Spec. 50)

- li. The microstructure of the parts was as follows:
  - a. The tubing and clevis had microstructures consisting of tempered martensite. These parts were quenched and tempered before welding.
  - b. The bolt contained spheroids of carbides and small islands of ferrite, with the major portion of the structure being tempered martensite. The presence of the carbide spheroids and the ferrite indicates that the austenitizing temperature and/or time used in heat treating the bolt were inadequate to convert the structure completely to austenite before quenching. The temperature may have been too low or the time in the furnace insufficient for the bolt to reach the desired temperature.
  - c. The microstructure of the nut consisted of fine pearlite and some ferrite, which is typical of normalized plain-carbon containing 0.5 per cent carbon.
- 5. The results of tests to determine tensile and hardness characteristics were as follows:

## . TENSILE PROPERTIES AND HARDNESS

Description	Yield Strength, 0.2% Offset, p.s.i.	Ultimate Strength, p.s.i.	Elongation, Per Cent in 2 in.	Hardness, Rockwell C	``
Tubing, 1.36" 0.D.	121,000 124,000	132,500 136,000	10.0 10.0	27	
Tubing, 0.98# 0.D.	140,000 137,000	150,000 149,000	10.0 11.0	<b>2</b> 8	
Clevis				32	
Solt :	88,500	120,000	20.0%	27.	•
Nut				25	
1	.05,000-130,000	127,000-140	,000 18-22	<b>2</b> 8	

o. This chromium-manganese-silicon steel has been investigated in the United States in the 1930's but has not found popularity here. The Soviets use the steel extensively in their airframes. The NIG-15 engine mount stabilizer spar, linkages, brackets, and other structural parts are made of this steel; the steel has also been used in the landing gear strut of the YAK-9.

-The end-

SECRET SEUKEI